

**Flood Control Project Maintenance  
Levee Inspections**

**LMA District Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Madera County FCWCA**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2010 Levee Inspection Results  
Madera County FCWCA**

Waterway		Bank	Unit Miles
Unit No. 01 Ash Slough		Right	2.41

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/28/2010 - 5/28/2010			
DWR Inspector	Herman Phillips			
Accompanied By	GABREIL SCOTT Madera County Flood Control			
	Mr. Ignacio Margo Madera County Flood Control			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Ash Slough						Right	2.41	05/28/2010 05/28/2010	Herman Phillips	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.03	0.03	Earthen Levee	Encroachments	WS	M	Debris	37.046593 ° -120.427382 °	37.046593 ° -120.427382 °	4
2	0.10	0.14	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	37.045658 ° -120.426818 °	37.045948 ° -120.425513 °	951
3	0.24	0.24	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.047502 ° -120.423747 °	37.047502 ° -120.423747 °	5
4	0.28	0.30	Earthen Levee	Encroachments	WS	M	Tree or limb	37.047812 ° -120.423155 °	37.047963 ° -120.422898 °	6
5	0.32	0.32	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.048187 ° -120.422693 °	37.048187 ° -120.422693 °	7
6	0.32	0.34	Earthen Levee	Encroachments	WS	M	Tree or limb	37.048223 ° -120.422642 °	37.048467 ° -120.422315 °	8
7	0.43	0.43	Earthen Levee	Encroachments	WS	M	Tree or limb	37.049355 ° -120.421203 °	37.049355 ° -120.421203 °	9
8	0.53	0.53	Earthen Levee	Encroachments	WS	M	Tree or limb	37.050335 ° -120.419965 °	37.050335 ° -120.419965 °	10
9	0.79	0.79	Earthen Levee	Encroachments	LS	M	Equipment	37.053287 ° -120.417445 °	37.053287 ° -120.417445 °	11
10	1.11	1.20	Supplemental	DWR Erosion Survey	WS	M	Inspector Comments: 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM2.57]	37.055596 ° -120.412647 °	37.055596 ° -120.412647 °	1 Y
11	1.46	1.52	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	37.059053 ° -120.409018 °	37.059390 ° -120.408050 °	12
12	1.52	1.52	Earthen Levee	Encroachments	WS	M	Garbage	37.058570 ° -120.407715 °	37.058563 ° -120.407702 °	952
13	2.37	2.39	Supplemental	DWR Erosion Survey	WS	M	Inspector Comments: 2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM3.8]	37.068570 ° -120.398620 °	37.068570 ° -120.398620 °	2 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Ash Slough	Right	2.41	05/28/2010 05/28/2010	Herman Phillips

Levee Mile Report Line	10
Start Levee Mile	1.11
End Levee Mile	1.20
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
2009: Site recommended as local maintenance issue, per Critical Levee Repair Office, Critical Erosion Sites Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM2.57]	
SJR2009_RM2.57A.JPG	



Levee Mile Report Line	10
Start Levee Mile	1.11
End Levee Mile	1.20
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
2009: Site recommended as local maintenance issue, per Critical Levee Repair Office, Critical Erosion Sites Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM2.57]	
SJR2009_RM2.57B.JPG	



Levee Mile Report Line	10
Start Levee Mile	1.11
End Levee Mile	1.20
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
2009: Site recommended as local maintenance issue, per Critical Levee Repair Office, Critical Erosion Sites Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM2.57]	
SJR2009_RM2.57C.JPG	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Ash Slough	Right	2.41	05/28/2010 05/28/2010	Herman Phillips

Levee Mile Report Line	10
Start Levee Mile	1.11
End Levee Mile	1.20
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
2009: Site recommended as local maintenance issue, per Critical Levee Repair Office, Critical Erosion Sites Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM2.57]	
SJR2009_RM2.57D.JPG	



Levee Mile Report Line	13
Start Levee Mile	2.37
End Levee Mile	2.39
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM3.8]	
SJR2009_S1 LM2.38 082508c.JPG	



Levee Mile Report Line	13
Start Levee Mile	2.37
End Levee Mile	2.39
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM3.8]	
SJR2009_S1 LM2.38 082508d.JPG	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Ash Slough	Right	2.41	05/28/2010 05/28/2010	Herman Phillips

Levee Mile Report Line	13
Start Levee Mile	2.37
End Levee Mile	2.39
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM3.8]	
SJR2009_S1 LM2.38 082508e.JPG	



Levee Mile Report Line	13
Start Levee Mile	2.37
End Levee Mile	2.39
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey
2009: Site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:NA0011U1RM3.8]	
SJR2009_Site 1 Unit 1 LM 2.39f.JPG	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2010 Levee Inspection Results  
Madera County FCWCA**

Waterway	Bank	Unit Miles
Unit No. 02 Ash Slough	Left	2.07

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/28/2010 - 5/28/2010			
DWR Inspector	Herman Phillips			
Accompanied By	Gabriel Scott			
	Mr. Ignacio Margo			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Ash Slough							Left	2.07	05/28/2010 05/28/2010	Herman Phillips
LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.16	0.17	Earthen Levee	Encroachments	LS	PO	Landscaping	37.046212 ° -120.424573 °	37.046303 ° -120.424332 °	6
2	0.27	0.28	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.046935 ° -120.422855 °	37.047068 ° -120.422645 °	8
3	0.27	0.29	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.046937 ° -120.422815 °	37.047192 ° -120.422517 °	21
4	0.45	0.53	Earthen Levee	Encroachments	LS	PO	Fences	37.048627 ° -120.420357 °	37.049342 ° -120.419370 °	11
5	0.79	0.84	Earthen Levee	Encroachments	LS	M	Equipment Inspector Comments: THE Land owner here has equipment within the easement landside however, most of the encroachments has been removed since last Inspection. All has not been removed.	37.053137 ° -120.417517 °	37.052745 ° -120.417695 °	26
6	0.79	0.79	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.053283 ° -120.417477 °	37.053283 ° -120.417477 °	27
7	1.04	1.24	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.055115 ° -120.414588 °	37.056050 ° -120.411178 °	3
8	1.49	1.49	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.058273 ° -120.408195 °	37.058273 ° -120.408195 °	2
9	1.52	1.52	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.058573 ° -120.407660 °	37.058573 ° -120.407660 °	1
10	1.53	1.55	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.058652 ° -120.407638 °	37.058802 ° -120.407350 °	25

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2010 Levee Inspection Results  
Madera County FCWCA**

Waterway		Bank	Unit Miles
Unit No. 03 Berenda Slough		Right	1.55

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/27/2010 - 5/27/2010			
DWR Inspector	Herman Phillips			
Accompanied By	Gabriela Scott Madera County Flood Control			
	Mr. Ignacio Margo Madera County Flood Control			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 03 Berenda Slough				Right	1.55	05/27/2010 05/27/2010	Herman Phillips	

  

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.14	0.14	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: 5/27/2010 The District was in process of mowing during this inspection.	36.996075 ° -120.371273 °	36.996075 ° -120.371272 °	2
2	0.29	0.33	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: The crown road way shall be keep free of any vegetation. The slopes appear to have been sprayed though the growth hasn't been removed from levee sections since 2008.	36.996112 ° -120.368558 °	36.996143 ° -120.367987 °	3
3	1.07	1.07	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	36.996613 ° -120.355055 °	36.996610 ° -120.354995 °	11
4	1.07	1.08	Earthen Levee	Encroachments	WS	M	Material	36.996568 ° -120.355028 °	36.996570 ° -120.354788 °	4
5	1.09	1.12	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	36.996618 ° -120.354538 °	36.996633 ° -120.354012 °	15
6	1.09	1.10	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	36.996620 ° -120.354535 °	36.996625 ° -120.354340 °	16
7	1.10	1.21	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	36.996587 ° -120.354515 °	36.996567 ° -120.352393 °	5
8	1.10	1.15	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	36.996582 ° -120.354410 °	36.996588 ° -120.353595 °	6
9	1.26	1.26	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	36.996632 ° -120.351463 °	36.996632 ° -120.351463 °	17
10	1.50	1.53	Earthen Levee	Animal Control	CR	M	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: At this levee section levee mile 1.50 I measured a section of levee in that area there were 15 holes on the water side 4 in the crown road way and 3 on the land side. Pictures taken.	36.996550 ° -120.347108 °	36.996583 ° -120.346683 °	8 Y
11	1.50	1.53	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	36.996557 ° -120.347102 °	36.996583 ° -120.346678 °	9

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Berenda Slough	Right	1.55	05/27/2010 05/27/2010	Herman Phillips

Levee Mile Report Line	10
Start Levee Mile	1.50
End Levee Mile	1.53
Location	Crown
Category	Earthen Levee
Item	Animal Control

There are several rodent holes in the shoulder and crown of the road way.

phillips\_s\_20100316\_001.jpg



Levee Mile Report Line	10
Start Levee Mile	1.50
End Levee Mile	1.53
Location	Crown
Category	Earthen Levee
Item	Animal Control

This photo show holes in crown and shoulder.

phillips\_s\_20100316\_002.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2010 Levee Inspection Results  
Madera County FCWCA**

Waterway		Bank	Unit Miles
Unit No. 04 Berenda Slough		Left	2.28

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/27/2010 - 5/27/2010			
DWR Inspector	Herman Phillips			
Accompanied By	Gabriela Scott			
	Mr. Ignacio Margo Madera Flood Control District			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Berenda Slough						Left	2.28	05/27/2010 05/27/2010	Herman Phillips

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.06	0.45	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: Did not see any rodent during this inspection, the weeds were too tall to see. District is in process of mowing this levee section.	36.995580 ° -120.372432 °	36.995610 ° -120.365297 °	2
2	0.48	0.48	Earthen Levee	Encroachments	WS	M	Tree or limb	36.995572 ° -120.364872 °	36.995570 ° -120.364760 °	6
3	1.02	1.02	Earthen Levee	Encroachments	WS	C	Tree or limb	36.995590 ° -120.355240 °	36.995602 ° -120.355228 °	9
4	1.06	1.06	Earthen Levee	Encroachments	LS	M	Debris	36.996612 ° -120.354873 °	36.996612 ° -120.354873 °	1
5	1.59	1.59	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.995910 ° -120.345293 °	36.995910 ° -120.345293 °	11
6	1.73	2.26	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	36.997343 ° -120.343633 °	37.003280 ° -120.337602 °	10

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected



**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2010 Levee Inspection Results  
Madera County FCWCA**

Waterway		Bank	Unit Miles
Unit No. 05 Fresno River		Right	9.20

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/27/2010 - 5/27/2010			
DWR Inspector	Herman Phillips			
Accompanied By	Mr. Greg Farley Madera Flood Control District			
	Mr. Ignacio Margo Madera Flood Control District			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 05 Fresno River						Right	9.20	05/27/2010 05/27/2010	Herman Phillips	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.05	4.02	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	36.978455 ° -120.367652 °	36.968149 ° -120.302316 °	1
2	0.05	4.02	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	36.978422 ° -120.367665 °	36.968149 ° -120.302316 °	6
3	0.19	0.26	Earthen Levee	Animal Control	CR	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	36.977998 ° -120.365077 °	36.977715 ° -120.363902 °	2
4	0.19	0.40	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	36.977998 ° -120.365077 °	36.976882 ° -120.361610 °	3
5	0.20	0.26	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	36.977967 ° -120.364960 °	36.977715 ° -120.363902 °	4
6	0.54	0.56	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	36.975520 ° -120.359788 °	36.975350 ° -120.359548 °	5
7	1.59	1.63	Earthen Levee	Animal Control	CR	M	Exterminate rodents and backfill and compact or grout burrows.	36.967923 ° -120.345818 °	36.967877 ° -120.345175 °	19
8	1.59	4.10	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.967928 ° -120.345813 °	36.968175 ° -120.300922 °	18
9	1.87	4.10	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.967870 ° -120.340830 °	36.968172 ° -120.300913 °	20
10	3.55	4.08	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	36.968135 ° -120.310465 °	36.968157 ° -120.301090 °	8
11	4.24	4.36	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	36.968138 ° -120.298362 °	36.968202 ° -120.296210 °	22
12	4.24	4.36	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.968135 ° -120.298355 °	36.968202 ° -120.296210 °	21
13	4.50	5.27	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	36.968230 ° -120.293665 °	36.968247 ° -120.279957 °	23
14	6.62	7.53	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	36.968557 ° -120.255757 °	36.969533 ° -120.239748 °	7
15	6.65	6.65	Earthen Levee	Encroachments	WS	C	Material Inspector Comments: Here at location is a earthen Dam operated by MID. This Dam should have been Taken out 11-01 the beginning of flood season. Levee mile 6.57 5-foot high 70-75-foot across from right bank to left bank. 36.968493-120.255125. Three photos taken.	36.968493 ° -120.255205 °	36.968493 ° -120.255205 °	28
16	7.61	7.76	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	36.969577 ° -120.238330 °	36.969725 ° -120.235783 °	12

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Fresno River							Right	9.20	05/27/2010 05/27/2010	Herman Phillips

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
17	8.53	8.54	Earthen Levee	Encroachments	LS	M	Debris	37.068720 ° -120.398500 °	36.372730 ° -120.221320 °	27
18	9.20	9.20	Earthen Levee	Encroachments	WS	C	Debris	36.973255 ° -120.211357 °	36.973937 ° -120.209598 °	26

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2010 Levee Inspection Results  
Madera County FCWCA**

Waterway		Bank	Unit Miles
Unit No. 06 Fresno River		Left	9.14

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/27/2010 - 5/27/2010			
DWR Inspector	Herman Phillips			
Accompanied By	Greg Farley Madera County Flood Control			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Madera County FCWCA**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 06 Fresno River						Left	9.14	05/27/2010 05/27/2010	Herman Phillips	
LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	2.73	2.82	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.967317 ° -120.324138 °	36.967302 ° -120.322640 °	13
2	3.33	3.33	Earthen Levee	Encroachments	LS	C	Debris	36.967458 ° -120.313557 °	36.967463 ° -120.313492 °	19
3	5.41	5.45	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.967550 ° -120.276208 °	36.967572 ° -120.275478 °	12
4	5.54	5.56	Earthen Levee	Encroachments	LS	C	Poles	36.967558 ° -120.273935 °	36.967558 ° -120.273810 °	10
5	5.55	5.55	Earthen Levee	Encroachments	LS	C	Debris	36.967502 ° -120.273837 °	36.967502 ° -120.273837 °	23
6	5.84	5.84	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.967538 ° -120.268660 °	36.967538 ° -120.268660 °	9
7	6.00	6.20	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.967530 ° -120.265732 °	36.967545 ° -120.262320 °	8
8	6.22	6.52	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.967572 ° -120.261918 °	36.967923 ° -120.256698 °	6
9	6.29	6.47	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	36.967635 ° -120.260798 °	36.967905 ° -120.257615 °	22
10	7.73	7.75	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	36.969048 ° -120.235258 °	36.969235 ° -120.234877 °	21
11	7.73	7.76	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	36.969167 ° -120.235215 °	36.969350 ° -120.234747 °	5

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor